

**MICROCHIP****PIC18F6527/6622/8527/8622**

## **PIC18F6527/6622/8527/8622 Rev. A1 Silicon Errata**

The PIC18F6527/6622/8527/8622 parts you have received conform functionally to the Device Data Sheet (DS39646B), except for the anomalies described below. Any Data Sheet Clarification issues related to the PIC18F6527/6622/8527/8622 devices will be reported in a separate Data Sheet errata. Please check the Microchip web site for any existing issues.

All of the issues listed here will be addressed in future revisions of the PIC18F6527/6622/8527/8622 silicon.

**The following silicon errata apply only to PIC18F6527/6622/8527/8622 devices with these Device/Revision IDs:**

Part Number	Device ID	Revision ID
PIC18F6527	01 0011 010	00000
PIC18F6622	01 0011 100	00000
PIC18F8527	01 0011 011	00000
PIC18F8622	01 0011 101	00000

The Device IDs (DEVID1 and DEVID2) are located at addresses 3FFFFEh:3FFFFFh in the device's configuration space. They are shown in hexadecimal in the format "DEVID2 DEVID1".

**TABLE 1: A/D CONVERTER CHARACTERISTICS: PIC18F6X27/6X22/8X27/8X22 (INDUSTRIAL, EXTENDED)  
PIC18LF6X27/6X22/8X27/8X22 (INDUSTRIAL)**

Param No.	Symbol	Characteristic	Min	Typ	Max	Units	Conditions
A06A	E0FF	Offset Error	—	—	±1.5	LSb	VREF = VREF+ and VREF-
A06	E0FF	Offset Error	—	—	±3.5	LSb	VREF = Vss and VDD

### **2. Module: EUSART**

In Synchronous mode, EUSART baud rates using SPBRGx values of '0' and '1' may not function correctly.

#### Work around

Use another baud rate configuration to generate the desired baud rate.

### **1. Module: A/D**

The A/D offset is greater than the specified limit in Table 28-26 of the Device Data Sheet. The updated conditions and limits are shown in **bold** text in Table 1.

#### Work around

Three work arounds exist.

1. Configure the A/D to use the VREF+ and VREF- pins for the voltage references. This is done by setting the VCFG<1:0> bits (ADCON1<5:4>).
2. Perform a conversion on a known voltage reference voltage and adjust the A/D result in software.
3. Increase system clock speed and adjust A/D settings accordingly. Higher system clock frequencies decrease offset error.

#### Date Codes that pertain to this issue:

All engineering and production devices.

### **3. Module: EUSART**

After the last received byte has been read from the EUSART receive buffer, RCREGx, the value is no longer valid for subsequent read operations. The RCREGx register should only be read once for each byte received.

#### Work around

After each byte is received from the EUSART, store the byte into a user variable. To determine when a byte is available to read from RCREGx, poll the RCIDL (BAUDCONx<6>) bit for a low-to-high transition or use the EUSART Receive Interrupt Flag, RC1IF (PIR1<5>).

# PIC18F6527/6622/8527/8622

---

## 4. Module: EUSART

In 9-Bit Asynchronous Full-Duplex Receive mode, received data may be corrupted if the TX9D bit (TXSTAx<0>) is not modified immediately after RCIDL (BAUDCONx<6>) is set.

### Work around

Only write to TX9D when a reception is not in progress (RCIDL = 1). No interrupt is associated with RCIDL, therefore, it must be polled in software to determine when TX9D can be updated.

## 5. Module: ECCP

PIC18F6XXX device's Configuration Word, CONFIG3L, is not unimplemented and will switch the ECCP2 output pin similar to the PIC18F8XXX devices if the Processor mode does not select Microcontroller mode.

### Work around

In MPLAB® IDE, program the PIC18F6XXX device as its PIC18F8XXX equivalent and assign the Processor mode bits (PM<1:0>) to '11' for Microcontroller mode.

## 6. Module: External Memory Bus

For PIC18F8XXX devices, the Stack Pointer may incorrectly increment during a table read operation if the external memory bus wait states are enabled (i.e., Configuration bit, WAIT, is clear (CONFIG3L<7> = 0) and WAIT<1:0> bits (MEMCON<5:4>) are not equal to '11').

### Work around

If using the external memory bus and performing TBLRD operations with a non-zero wait state (CONFIG3L<7> = 0 and WAIT<1:0> (MEMCON<5:4>) are not equal to '11'), disable interrupts by clearing the GIE/GIEH (INTCON<7>) and PEIE/GIEL (INTCON<6>) bits prior to executing any TBLRD operation.

## 7. Module: MSSP

In SPI mode, the Buffer Full flag (BF bit in the SSPxSTAT register), the Write Collision Detect bit (WCOL bit in SSPxCON1) and the Receive Overflow Indicator bit (SSPOV in SSPxCON1) are not reset upon disabling the SPI module (by clearing the SSPEN bit in the SSPxCON1 register).

For example, if SSPxBUF is full (BF bit is set) and the MSSP module is disabled and re-enabled, the BF bit will remain set. In SPI Slave mode, a subsequent write to SSPxBUF will result in a write collision. Also, if a new byte is received, a receive overflow will occur.

### Work around

Ensure that if the buffer is full, SSPxBUF is read (thus clearing the BF flag) and WCOL is clear before disabling the MSSP module. If the module is configured in SPI Slave mode, ensure that the SSPOV bit is clear before disabling the module.

## 8. Module: Timer1

In 16-Bit Asynchronous Counter mode or 16-Bit Asynchronous Oscillator mode, the TMR1H and TMR3H buffers do not update when TMRxL is read. This issue only affects reading the TMRxH registers. The timers increment and set the interrupt flags as expected. The Timer registers can also be written as expected.

### Work around

Use 8-bit mode by clearing the RD16 (T1CON<7>) bit or use the synchronization option by clearing T1SYNC (T1CON<2>).

## 9. Module: PORTE

The RE4 pin latch remains at tri-state when the ECCPMX Configuration bit is clear and selects PORTH.

### Work around

This issue will be corrected in a future revision of silicon.

## 10. Module: EUSART

In rare situations, one or more extra zero bytes have been observed in a packet transmitted by the module operating in Asynchronous mode. The actual data is not lost or corrupted; only unwanted (extra) zero bytes are observed in the packet.

This situation has only been observed when the contents of the transmit buffer, TXREGx, are transferred to the TSRx during the transmission of a Stop bit. For this to occur, three things must happen in the same instruction cycle:

- TXREGx is written to;
- the baud rate counter overflows (at the end of the bit period); and
- a Stop bit is being transmitted (shifted out of TSRx).

### Work around

If possible, do not use the module's double buffer capability. Instead, load the TXREGx register when the TRMT bit (TXSTAx<1>) is set, indicating the TSRx is empty.

If double-buffering is used and back-to-back transmission is performed, then load TXREGx immediately after TXxIF is set or wait 1-bit time after TXxIF is set. Both solutions prevent writing TXREGx while a Stop bit is transmitted. Note that TXxIF is set at the beginning of the Stop bit transmission.

## 11. Module: EUSART

When performing back-to-back transmission in 9-bit mode (TX9D bit in the TXSTAx register is set), the second byte may be corrupted if it is written into TXREGx immediately after the TMRT bit is set.

### Work around

Execute a software delay, at least one-half the transmission's bit time, after TMRT is set and prior to writing subsequent bytes into TXREGx.

### Date Codes that pertain to this issue:

All engineering and production devices.

If transmission is intermittent, then do the following:

- Wait for the TRMT bit to be set before loading TXREGx
- Alternatively, use a free timer resource to time the baud period. Set up the timer to overflow at the end of the Stop bit, then start the timer when you load the TXREGx. Do not load the TXREGx when timer is about to overflow.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 12. Module: EUSART

With the auto-wake-up option enabled by setting the WUE (BAUDCONx<1>) bit, the RCxIF bit will become set on a high-to-low transition on the RXx pin. However, the WUE bit may not clear within 1 TCY of a low-to-high transition on RXx. While the WUE bit is set, reading the receive buffer, RCREGx, will not clear the RCxIF interrupt flag. Therefore, the first opportunity to automatically clear RCxIF by reading RCREGx may take longer than expected.

**Note:** RCxIF can only be cleared by reading RCREGx.

### Work around

There are two work arounds available:

1. Clear the WUE bit in software, after the wake-up event has occurred, prior to reading the receive buffer, RCREGx.
2. Poll the WUE bit and read RCREGx after the WUE bit is automatically cleared.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 13. Module: MSSP (SPI Mode)

In SPI mode, the SDOx output may change after the inactive clock edge of the bit '0' output. This may affect some SPI components that read data over 300 ns after the inactive edge of SCKx.

### Work around

None

### Date Codes that pertain to this issue:

All engineering and production devices.

# PIC18F6527/6622/8527/8622

## 14. Module: MSSP (SPI Mode)

In SPI mode, the Buffer Full Status bit, BF (SSPxSTAT<0>), should not be polled in software to determine when the transfer is complete.

### Work around

Copy the SSPxSTAT register into a variable and perform the bit test on the variable. In Example 1, SSPxSTAT is copied into the working register where the bit test is performed (SSP1STAT is shown, but this process is also applicable to SSP2STAT).

### EXAMPLE 1:

```
loop_MSB:  
    MOVF    SSP1STAT, W  
    BTFSS   WREG, BF  
    BRA     loop_MSB
```

A second option is to poll the appropriate Master Synchronous Serial Port Interrupt Flag bit, SSPxIF. This bit can be polled and will set when the transfer is complete.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 15. Module: MSSP (SPI Mode)

In SPI Master mode, a write collision may occur if the SSPxBUF register is loaded immediately after a transfer is complete. This may be caused by an inadequate delay between the MSSP Interrupt Flag bit (SSPxIF) or the Buffer Full bit (BF) being set, and SSPxBUF being written to.

This has only been observed when the SPI clock is operating at Fosc/64 or ((Timer2)/2) (SSPxCON1<3:0> = 001x).

### Work around

Add a software delay of one SCKx period after detecting the completed transfer, and prior to updating the contents of SSPxBUF.

Also verify that the Write Collision bit (WCOL) is clear after writing SSPxBUF. If WCOL is set, clear the bit in software and rewrite the contents of SSPxBUF.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 16. Module: MSSP (I<sup>2</sup>C™ Mode)

In its current implementation, the I<sup>2</sup>C Master mode operates as follows:

- The Baud Rate Generator for I<sup>2</sup>C in Master mode is slower than the rates specified in Table 17-3 of the Device Data Sheet.

For this revision of silicon, use the values shown in Table 2 (below) in place of those shown in Table 17-3 of the Device Data Sheet. The differences are shown in **bold** text.

- Use the following formula in place of the one shown in Register 19-4 (SSPxCON1) of the Device Data Sheet for bit description SSPM3:SSPM0 = 1000.

$$\text{SSPxADD} = \text{INT}((\text{FcY}/\text{FsCL}) - (\text{FcY}/1.111 \text{ MHz})) - 1$$

### Date Codes that pertain to this issue:

All engineering and production devices.

TABLE 2: I<sup>2</sup>C™ CLOCK RATE w/BRG

Fosc	FcY	FcY * 2	BRG Value	FsCL (2 Rollovers of BRG)
<b>40 MHz</b>	10 MHz	20 MHz	<b>0Eh</b>	400 kHz <sup>(1)</sup>
<b>40 MHz</b>	10 MHz	20 MHz	<b>15h</b>	312.5 kHz
<b>40 MHz</b>	10 MHz	20 MHz	<b>59h</b>	100 kHz
<b>16 MHz</b>	4 MHz	8 MHz	<b>05h</b>	400 kHz <sup>(1)</sup>
<b>16 MHz</b>	4 MHz	8 MHz	<b>08h</b>	308 kHz
<b>16 MHz</b>	4 MHz	8 MHz	<b>23h</b>	100 kHz
<b>4 MHz</b>	1 MHz	2 MHz	<b>01h</b>	333 kHz <sup>(1)</sup>
<b>4 MHz</b>	1 MHz	2 MHz	<b>08h</b>	100 kHz
<b>4 MHz</b>	1 MHz	2 MHz	00h	1 MHz <sup>(1)</sup>

**Note 1:** The I<sup>2</sup>C™ interface does not conform to the 400 kHz I<sup>2</sup>C specification (which applies to rates greater than 100 kHz) in all details, but may be used with care where higher rates are required by the application.

## 17. Module: MSSP (I<sup>2</sup>C Mode)

It has been observed that, following a Power-on Reset, I<sup>2</sup>C mode may not initialize properly by just configuring the SCLx and SDAx pins as either inputs or outputs. This has only been seen in a few unique system environments.

A test of a statistically significant sample of pre-production systems, across the voltage and current range of the application's power supply, should indicate if a system is susceptible to this issue.

### Work around

Before configuring the module for I<sup>2</sup>C operation:

1. Configure the SCLx and SDAx pins as outputs by clearing their corresponding TRIS bits.
2. Force SCLx and SDAx low by clearing the corresponding LAT bits.
3. While keeping the LAT bits clear, configure SCLx and SDAx as inputs by setting their TRIS bits.

Once this is done, use the SSPxCON1 and SSPxCON2 registers to configure the proper I<sup>2</sup>C mode as before.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 18. Module: MSSP (I<sup>2</sup>C Mode)

In I<sup>2</sup>C Master mode, the RCEN bit is set by software to begin data reception, and cleared by the peripheral after a byte is received. After a byte is received, the device may take up to 80 Tcy to clear RCEN and 800 Tcy during emulation.

### Work around

Single byte receptions are typically not affected, since the delay between byte receptions typically is long enough for the RCEN bit to clear. For multiple byte receptions, the software must wait until the bit is cleared by the peripheral before the next byte can be received.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 19. Module: ECCP (PWM Mode)

When the PWM auto-shutdown feature is configured for automatic restart by setting the PxRSEN bit (ECCPxDEL<7>), the pulse may terminate immediately in a shutdown event. In addition, the pulse may restart within the period if the shutdown condition expires. This may result in the generation of short pulses on the PWM output(s).

### Work around

Configure the auto-shutdown for software restart by clearing the PxRSEN bit. The PWM can be re-enabled by clearing the ECCPxASE bit (ECCPxAS<7>) after the shutdown condition expires.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 20. Module: ECCP (PWM Mode)

When configured for half-bridge operation with dead band (CCPxCON<7:6> = 10), the PWM output may be corrupted for certain values of the PWM duty cycle. This can occur when these additional criteria are also met:

- a non-zero, dead-band delay is specified (PxDC6:PxDc0 > 0); and
- the duty cycle has a value of 0 through 3, or  $4n + 3$  ( $n \geq 1$ ).

### Work around

None.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 21. Module: CCP (PWM Mode)

Timer4 is not available as a clock source for either CCP4 or CCP5 in any PWM mode (CCPxCON<3:2> = 11). Selecting Timer4 as the module's clock source may cause the PWM output to stop generating pulses.

### Work around

To use CCP4 or CCP5 in PWM mode, use only Timer2 as the clock source (T3CON<6,3> = 00).

### Date Codes that pertain to this issue:

All engineering and production devices.

# PIC18F6527/6622/8527/8622

---

## 22. Module: Reset

This version of silicon does not support the functionality described in Note 1 of parameter D002 in **Section 28.1 “DC Characteristics: Supply Voltage”** of the data sheet. The RAM content may be altered during a Reset event if the following conditions are met.

- Device is accessing RAM.
- Asynchronous Reset (i.e., WDT, BOR or  $\overline{\text{MCLR}}$  occurs when a write operation is being executed (start of a Q4 cycle).

### Work around

None.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 23. Module: External Memory Bus

The  $A_{19:16}$  EMB address lines and Read/Write control pins ( $OE$ ,  $WRH$  and  $WRL$ ) are released to their respective inactive states at the same time, violating the timing condition mentioned in Figure 28-8 and Figure 28-9 in the Device Data Sheet. This may result in a peripheral device on the bus detecting an address change when a write/read is initiated. The bus capacitance and signal delay on the address and control lines can affect the probability of invalid detection.

### Work around

Two work arounds are available:

1. Use a latch based on the falling edge of ALE to hold the  $A_{19:16}$  signals.
2. Add a delay circuit to extend the valid time for  $A_{19:16}$  signals to ensure the address is valid until read/write signals go inactive.

## REVISION HISTORY

### Rev A Document (12/2005)

Original version of this document. Contains silicon issues: 1 (A/D), 2-4 (EUSART), 5 (ECCP), 6 (External Memory Bus), 7 (MSSP), 8 (Timer1) and 9 (PORTE).

### Rev B Document (8/2006)

Added silicon issues 10-12 (EUSART), 13-15 (MSSP – SPI Mode), 16-18 (MSSP – I<sup>2</sup>C Mode), 19-20 (ECCP – PWM Mode), 21 (CCP – PWM Mode), 22 (Reset) and 23 (External Memory Bus).

# **PIC18F6527/6622/8527/8622**

---

---

**NOTES:**

---

**Note the following details of the code protection feature on Microchip devices:**

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

---

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. **MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE.** Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

#### **Trademarks**

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, KEELOQ, microID, MPLAB, PIC, PICmicro, PICSTART, PRO MATE, PowerSmart, rfPIC, and SmartShunt are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AmpLab, FilterLab, Migratable Memory, MXDEV, MXLAB, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, ECAN, ECONOMONITOR, FanSense, FlexROM, fuzzyLAB, In-Circuit Serial Programming, ICSP, ICEPIC, Linear Active Thermistor, Mindi, MiWi, MPASM, MPLIB, MPLINK, PICtail, PICDEM, PICDEM.net, PICLAB, PICtail, PowerCal, PowerInfo, PowerMate, PowerTool, REAL ICE, rFLAB, rfPICDEM, Select Mode, Smart Serial, SmartTel, Total Endurance, UNI/O, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2006, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.



Printed on recycled paper.

---

**QUALITY MANAGEMENT SYSTEM  
CERTIFIED BY DNV  
=ISO/TS 16949:2002=**

*Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona, Gresham, Oregon and Mountain View, California. The Company's quality system processes and procedures are for its PICmicro® 8-bit MCUs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.*



# MICROCHIP

## WORLDWIDE SALES AND SERVICE

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://support.microchip.com>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

**Atlanta**

Alpharetta, GA  
Tel: 770-640-0034  
Fax: 770-640-0307

**Boston**

Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

**Chicago**

Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

**Dallas**

Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

**Detroit**

Farmington Hills, MI  
Tel: 248-538-2250  
Fax: 248-538-2260

**Kokomo**

Kokomo, IN  
Tel: 765-864-8360  
Fax: 765-864-8387

**Los Angeles**

Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608

**Santa Clara**

Santa Clara, CA  
Tel: 408-961-6444  
Fax: 408-961-6445

**Toronto**

Mississauga, Ontario,  
Canada  
Tel: 905-673-0699  
Fax: 905-673-6509

### ASIA/PACIFIC

**Asia Pacific Office**  
Suites 3707-14, 37th Floor  
Tower 6, The Gateway  
Habour City, Kowloon  
Hong Kong  
Tel: 852-2401-1200  
Fax: 852-2401-3431

**Australia - Sydney**  
Tel: 61-2-9868-6733  
Fax: 61-2-9868-6755

**China - Beijing**  
Tel: 86-10-8528-2100  
Fax: 86-10-8528-2104

**China - Chengdu**  
Tel: 86-28-8676-6200  
Fax: 86-28-8676-6599

**China - Fuzhou**  
Tel: 86-591-8750-3506  
Fax: 86-591-8750-3521

**China - Hong Kong SAR**  
Tel: 852-2401-1200  
Fax: 852-2401-3431

**China - Qingdao**  
Tel: 86-532-8502-7355  
Fax: 86-532-8502-7205

**China - Shanghai**  
Tel: 86-21-5407-5533  
Fax: 86-21-5407-5066

**China - Shenyang**  
Tel: 86-24-2334-2829  
Fax: 86-24-2334-2393

**China - Shenzhen**  
Tel: 86-755-8203-2660  
Fax: 86-755-8203-1760

**China - Shunde**  
Tel: 86-757-2839-5507  
Fax: 86-757-2839-5571

**China - Wuhan**  
Tel: 86-27-5980-5300  
Fax: 86-27-5980-5118

**China - Xian**  
Tel: 86-29-8833-7250  
Fax: 86-29-8833-7256

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-4182-8400  
Fax: 91-80-4182-8422

**India - New Delhi**  
Tel: 91-11-4160-8631  
Fax: 91-11-4160-8632

**India - Pune**  
Tel: 91-20-2566-1512  
Fax: 91-20-2566-1513

**Japan - Yokohama**  
Tel: 81-45-471-6166  
Fax: 81-45-471-6122

**Korea - Gumi**  
Tel: 82-54-473-4301  
Fax: 82-54-473-4302

**Korea - Seoul**  
Tel: 82-2-554-7200  
Fax: 82-2-558-5932 or  
82-2-558-5934

**Malaysia - Penang**  
Tel: 60-4-646-8870  
Fax: 60-4-646-5086

**Philippines - Manila**  
Tel: 63-2-634-9065  
Fax: 63-2-634-9069

**Singapore**  
Tel: 65-6334-8870  
Fax: 65-6334-8850

**Taiwan - Hsin Chu**  
Tel: 886-3-572-9526  
Fax: 886-3-572-6459

**Taiwan - Kaohsiung**  
Tel: 886-7-536-4818  
Fax: 886-7-536-4803

**Taiwan - Taipei**  
Tel: 886-2-2500-6610  
Fax: 886-2-2508-0102

**Thailand - Bangkok**  
Tel: 66-2-694-1351  
Fax: 66-2-694-1350

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-3910  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4450-2828  
Fax: 45-4485-2829

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**UK - Wokingham**  
Tel: 44-118-921-5869  
Fax: 44-118-921-5820