



November 11<sup>th</sup>, 2013

## C8051F388-B Errata

Erratum #	Title	Impact	Affected Revision
1	External Oscillator on 32-pin packages	Major	Revision A

Impact definition: Each erratum is marked with an impact, as defined below:

- Minor – Workaround exists.
- Major – Errata that do not conform to the data sheet or standard.
- Information – The device behavior is not ideal but acceptable. Typically, the data sheet will be changed to match the device behavior.

1. **Description:** The external oscillator circuit is non-functional on the 32-pin packages in C, RC, and Crystal oscillator modes. The external CMOS clock modes are functional. The affected part numbers are: C8051F389-GQ, C8051F389-GM, C8051F38B-GQ, C8051F38B-GM.

**Impact:** The external oscillator cannot be used to generate a clock when used in the C, RC or Crystal modes on the affected devices.

**Workaround:** One of the internal oscillators or an external CMOS clock may be used to provide a clock to the device and/or its peripherals.

**Resolution:** Revision B of the device will allow the use of the external oscillator in C, RC and Crystal modes.