



JIC-950C Quick Clip Insertion Tool

(Used for terminating jumpers on Quick Clip 3 & 4 beam terminals)



DIRECTIONS:

1. Insert wire into hole at the top of the bit as shown
2. Bend wire over slot and down the side of the tool
3. Push tool straight into terminal
4. Withdraw tool



OK Industries
Div. of Jonard Industries

134 Marbledale Road • Tuckahoe • NY 10707
Tel: 914-793-0700 • Fax: 914-793-4527 • sales@jonard.com