


APPLICA	BLE STAN	DAKD						1			
	OPERATING TEMPERATUR	RE RANGE	-35 °C TO +85°C (NC	TE1)		RAGE	IRE RANGE	-10	°C TO +60°C (1	VOTE3	)
RATING	OPERATING	IL NANGE	200/ TO 000/ (NO	TE3\		RAGE	IL NANGE	400/	TO 700/ /	NOTE:	)\
RATING	HUMIDITY RANGE		20% TO 80% (NO	HUIW		IDITY R	ANGE	40%	40% TO 70% (NO		
	APPLICABLE CONNECTOR		DF57H-4S-1.2C(#	#)	CUF	CURRENT			AWG 28 : 1.5A AWG :		
	VOLTAGE		50 V AC/DC					AWG 32	::U.&A AW	: 34 <del>ق</del> ــــــــــــــــــــــــــــــــــــ	U.5A
			SPEC	IFIC/		NS					
l I	EM		TEST METHOD				RE	QUIREMEN	ITS	QT	- AT
CONSTR	RUCTION										
GENERAL E	XAMINATION	VISUALLY AND BY MEASURING INSTRUMENT.					RDING TO	DRAWING.		X	X
MARKING		CONFIRMED VISUALLY.								X	X
		CTERISTICS									
CONTACT RESISTANCE MILLIVOLT LEVEL METHOD		20mV MAX, 1mA (DC or 1000Hz).					10 mΩ MAX.				-
INSULATION RESISTANCE		100 V DC.					0 MΩ MIN.				<u> </u>
VOLTAGE PROOF		500 V AC FOR 1 min.					NO FLASHOVER OR BREAKDOWN.				
MECHAN	NICAL CHA	RACTI	ERISTICS			•					•
MECHANIC		30 TIMES INSERTION AND EXTRACTION.					①CONTACT RESISTANCE: 20 mΩ MAX.				
OPERATION							②NO DAMAGE, CRACK OR LOOSENESS OF PARTS.				
CONTACT II	NSERTION TION FORCES	IT TAKES OUT AND INSERTS WITH A CONFORMITY CONNECTOR.					①INSERTION FORCE: 24.0N MAX.				
VIBRATION	TION TORCES	FREQUENCY 10 TO 55 Hz, SINGLE AMPLITUDE					②EXTRACTION FORCE: 1.2N MIN. ①NO ELECTRICAL DISCONTINUITY OF 1 μ s.				
SHOCK		0.75 mm, AT 10 CYCLES FOR 3 DIRECTION.  490 m/s² DURATION OF PULSE 11 ms AT 3 TIMES FOR 3					②NO DAMAGE, CRACK OR LOOSENESS OF PARTS.				
SHOCK		DIRECTIO		I 3 IIWE	5 FUR 3					X	
ENVIRO	NMENTAL		ACTERISTICS								
DAMP HEAT	TE)	EXPOSED AT 40 ± 2°C , 90 TO 95 %, 96 h.				①CONTACT RESISTANCE: 20 mΩ MAX.				X	-
(STEADY STA	(IE)	(AFTER LEAVING THE ROOM TEMPERATURE FOR 1~2h.)					②INSULATION RESISTANCE: 100 MΩ MIN. ③NO DAMAGE, CRACK OR LOOSENESS OF PARTS.				
RAPID CHANGE OF TEMPERATURE		TEMPERATURE -55°C→ +85°C				_	<u>`</u>		20 m Ω MAX.	_	+-
		TIME					LATION RE	SISTANCE	: 100 MΩ MIN.		
		UNDER 5	CYCLES. NSFERRING TIME OF THE TAI	NK IS 2~	·3 min)	3NO D	AMAGE, CRA	CK OR LOOS	ENESS OF PARTS	3.	
		`	EAVING THE ROOM TEMPERATUR		,						
RESISTANCE		1 '	W SOLDERING			1		OF CASE O		X	T -
SOLDERING	HEAT	≪REFLOW TIME≫ NUMBER OF REFLOW CYCLES : 2 CYCLES MAX.				EXCESSIVE LOOSENESS OF THE TERMINALS.					
			ON ABOVE 220 °C, 60 sec. I								
			EMPERATURE: 250°C 10 sec.	MAX.							
			HEAT TIME≫ AT TEMPERATURE(MIN) :150 °	°C							
			AT TEMPERATURE (MAX) :180 °								
			AT TIME(MIN) : 90 sec.								
			AT TIME(MAX) : 120 sec. ALSOLDERING								
		1	RING IRON TEMPERATURE :3:	50±10℃,	,						
			RING TIME : 3sec.								
SOLDERABIL	ITV	-	RENGTH ON CONTACT.  NG TEMPERATURE : 245°C			NEW/III	VIEODM CO	ATING OF S	OLDED SHALL	+	+_
OOLDENABIL		DURATION OF IMMERSION :SOLDERING, FOR 5 sec.				NEW UNIFORM COATING OF SOLDER SHALL COVER MINIMUM OF 95 % OF THE SURFACE BEING IMMERSED.				X	
NOTE 1: INCL	UDE THE TEMI	L PERATURE	RISING BY CURRENT.			IDEIIAG I	IVIIVIERSED.				
NOTE2:NO CO		NDITION (	OF LONG TERM STORAGE F		ISED DE		PEEOD E	OCD ON DO	ADD AETED		
			ND HUMIDITTY RANGE IS APP							r CD D	JAND ,
COUN	T D	ESCRIPTI	ON OF REVISIONS		DESIC	SNED		CHE	CKED	D	ATE
REMARKS							APPROVE	D K	I. AKIYAMA	_	03. 19
							CHECKE	D H	K. UMEHARA	12.	03. 19
Unless other	erwise speci	fied. refer	to JIS C 5402.			DESIGNE			TS. KUMAZAWA		03. 19
<u> </u>							DRAWN		S. KUMAZAWA		03.19
Note QT:Q	ualification Tes	st AT:Ass	urance Test X:Applicable Te	st	D	RAWIN	G NO.		LC4-34390		
HS.	S		PART NO.		DF57H-4P-1. 2V (21)						
	HIROSE ELECTRIC CO., LTD.				CODE	E NO.	CL666-0106-2-21			Δ	1/1






## DF57 Series Mating / Unmating Operation Instruction


①By positioning the convexity of the socket sides to the header concavity, align the centers of the socket and the header in pitch direftion.



②Slightly press the socket down at cable side to tilted angle.




@Press down at the lever side with stabilizing t he cable side to insert. Mating completes.




## Unmating


⊕Hook the lever with finger nail.



②Lift up to the upper difrection and friction lock is released.



③Lift up to the upper direction and positive lock is released. Removal completes.



	DRAWING NO.	EDC3-343906-01	
<b>H</b> 75	PART NO.	DF57H-4P-1.2V(21	)
	CODE NO.	CL666-0106-2-21	3/3