





DRAWING FOR REFERENCE: This is subject to change without notice
08/11/2012



DRAWING FOR PACKING



B (FREE)



- NOTE 1 1 TRAY:30 CONNECTORS
2 SETTING POSITION OF CONNECTORS IN THE TRAY SHALL BE ARRANGED
IN ACCORDANCE WITH DRAWING.
3 REMOVE THE VACUUM PICK-UP TAPE AFTER MOUNTING THE CONNECTOR.
4 THE DIMENSIONS IN PARENTHESES ARE FOR REFERENCE.

2	POLYIMIDE	(TAPE FOR VACUUM PICK-UP)						
1	PS	TRAY		3	(CONNECTOR)			
NO.	MATERIAL	FINISH . REMARKS		NO.	MATERIAL	FINISH . REMARKS		
UNITS mm		SCALE 1 : 2	COUNT	DESCRIPTION OF REVISIONS		DESIGNED	CHECKED	DATE
			APPROVED : HS. OKAWA 07. 05. 31		DRAWING NO. EDC3-082425-23			
			CHECED : HS. OZAWA 07. 05. 31		PART NO. FX2-100S-1. 27SVL (96)			
			DESIGNED : KT. DOI 07. 05. 31		CODE NO. CL572-2158-0-96			
	HIROSE ELECTRIC CO., LTD.	DRAWN : TS. MIYAKI 07. 05. 28						