

IDENTIFY PART AS PER SPEC. (7.1.1) IN VIEW 1. LEGAL HEALTH, SAFETY AND ENVIRONMENTAL CONSIDERATIONS MAY APPLY TO THE MATERIALS SPECIFIED ON THIS DOCUMENT. REFER TO ENGLISH ISG MATERIAL SPEC. (10.1) FOR METHOD. REFER TO PARA 3.3.3. INCLUDE VENDOR SYMBOLS AND EXISE PART IS DEMONSTRATED.


576258
NUMBER

3/4 ANGLE (AMERICAN) PROJECTION DIMENSIONS IN METRIC DO NOT SCALE PRINT

AMP & GREAT BRITAIN LTD. THE INFORMATION CONTAINED HEREIN IS UNCLASSIFIED EXCEPT WHERE SHOWN OTHERWISE.

PRINT 5151

REV ENGINEER ECN DATE REV ENGINEER ECN DATE SHT 1 OF 2



REV	ENGINEER	ECN	DATE	REV	ENGINEER	ECN	DATE	SHT	1	OF	2
1	M. CLIFFORD	EB00-0212-99	21-04-99	1	S. J. MASSIE	13032	24-02-93	111	43	112	157
2	J. LOFTHOUSE	EB00-0143-92	20-03-92	2	S. J. MASSIE	13012	04-02-93	Rc	56	58	
3	J. LOFTHOUSE	EB00-0268-95	03-06-95	3	S. J. MASSIE	12999	25-01-93	100	43		
4	J. LOFTHOUSE	EB00-0170-94	19-03-94	4	S. J. MASSIE	12933	29-10-92	REMOVE BURRS. BREAK SHARP EDGES TO 100 MAX.			
5	R. SOUTHEES	13254	23-06-95	5	S. J. MASSIE	12923	22-10-92	REMOVE BURRS. BREAK SHARP EDGES TO 100 MAX.			
6	S. J. MASSIE	13402	26-05-94	6	S. J. MASSIE	12911	03-10-92	REMOVE BURRS. BREAK SHARP EDGES TO 100 MAX.			
7	S. J. MASSIE	13261	12-04-94	7	S. J. MASSIE	12935	21-04-92	REMOVE BURRS. BREAK SHARP EDGES TO 100 MAX.			
8	S. J. MASSIE	13229	10-08-93	8	S. J. MASSIE	12661	14-02-92	REMOVE BURRS. BREAK SHARP EDGES TO 100 MAX.			
9	S. J. MASSIE	13149	13-05-93	9	S. J. MASSIE	12642	31-01-92	REMOVE BURRS. BREAK SHARP EDGES TO 100 MAX.			
10	S. J. MASSIE	13097	01-04-93	10	S. J. MASSIE	12638	22-01-92	REMOVE BURRS. BREAK SHARP EDGES TO 100 MAX.			
11	S. J. MASSIE	13097	01-04-93	11	S. J. MASSIE	AS DYN	16-09-91	REMOVE BURRS. BREAK SHARP EDGES TO 100 MAX.			

NOTES:
1. TOP EDGES TO REMAIN SHARP. REMOVE BURRS ONLY.

REV	ENGINEER	ECN	DATE	REV	ENGINEER	ECN	DATE	SHT	1	OF	2
1	M. CLIFFORD	EB00-0212-99	21-04-99	1	S. J. MASSIE	13032	24-02-93	111	43	112	157
2	J. LOFTHOUSE	EB00-0143-92	20-03-92	2	S. J. MASSIE	13012	04-02-93	Rc	56	58	
3	J. LOFTHOUSE	EB00-0268-95	03-06-95	3	S. J. MASSIE	12999	25-01-93	100	43		
4	J. LOFTHOUSE	EB00-0170-94	19-03-94	4	S. J. MASSIE	12933	29-10-92	REMOVE BURRS. BREAK SHARP EDGES TO 100 MAX.			
5	R. SOUTHEES	13254	23-06-95	5	S. J. MASSIE	12923	22-10-92	REMOVE BURRS. BREAK SHARP EDGES TO 100 MAX.			
6	S. J. MASSIE	13402	26-05-94	6	S. J. MASSIE	12911	03-10-92	REMOVE BURRS. BREAK SHARP EDGES TO 100 MAX.			
7	S. J. MASSIE	13261	12-04-94	7	S. J. MASSIE	12935	21-04-92	REMOVE BURRS. BREAK SHARP EDGES TO 100 MAX.			
8	S. J. MASSIE	13229	10-08-93	8	S. J. MASSIE	12661	14-02-92	REMOVE BURRS. BREAK SHARP EDGES TO 100 MAX.			
9	S. J. MASSIE	13149	13-05-93	9	S. J. MASSIE	12642	31-01-92	REMOVE BURRS. BREAK SHARP EDGES TO 100 MAX.			
10	S. J. MASSIE	13097	01-04-93	10	S. J. MASSIE	12638	22-01-92	REMOVE BURRS. BREAK SHARP EDGES TO 100 MAX.			
11	S. J. MASSIE	13097	01-04-93	11	S. J. MASSIE	AS DYN	16-09-91	REMOVE BURRS. BREAK SHARP EDGES TO 100 MAX.			

ANY ILL. COMBINATION

